

As the owner of a 2002 model year Buick Rendezvous, your satisfaction with our product is very important to us.

This letter is intended to make you aware that some 2002 model year Buick Rendezvous vehicles may develop a small crack at the base of the fuel fill tube near the fuel tank that can allow fuel vapors to escape and cause liquid fuel to drop to the ground during refueling and normal driving.

Do not take your vehicle to your Buick dealer as a result of this letter unless you believe that your vehicle has the condition as described above.


What We Have Done: General Motors is providing owners with additional protection for the condition described above. If this condition occurs on your 2002 Buick Rendezvous within 10 years of the date your vehicle was originally placed in service or 150,000 miles, whichever occurs first, the condition will be repaired for you at **no charge**.

What You Should Do: Repairs and adjustments qualifying under this special coverage must be performed by a General Motors dealer. You may want to call the service department at your dealer to find out how long they will need to have your vehicle so that you may schedule the appointment at a time that is convenient for you. This will also allow your dealer to order parts if they are not already in stock. Keep this letter with your other important glove box literature for future reference.

Reimbursement: The enclosed form explains what reimbursement is available and how to request reimbursement if you have paid for repairs for the special coverage condition.

If you have any questions or need any assistance, just contact your dealer or the Buick Customer Assistance Center between the hours of 8:00 AM and 11:00 PM, EST, Monday through Friday. They can be reached at 1.866.608.8080 (TTY 1.800.832.8425).

We are sorry for any inconvenience you may experience; however we have taken this action in the interest of your continued satisfaction with our products.



Scott Lawson
General Director,
Customer and Relationship Services



Enclosure
07203